

Exhibit C

Site Photographs

1. Former AMD building prior to demolition by TWC; transformers are behind fence (6/18/05)
2. Former AMD building adjacent to the Daycare Center (June 18, 2005)
3. Transformer prior to damage (June 18, 2005)
4. Fill port, oil level and other gauges on transformer (July 15, 2005)
5. Transformer marked "Perclene Filled" (July 15, 2005)
6. Damaged transformer is placed on demolition debris pile (July 15, 2005)
7. Damaged transformer and demolition debris (July 15, 2005)
8. Damaged transformer wrapped with plastic (July 19, 2005)
9. Drums containing PCE and roll-off bin containing PCE-contaminated debris (July 19, 2005)

#1 - Former AMD building prior to demolition by TWC; transformers are behind fence (6/18/2005)



#2 - Former AMD building adjacent to the Daycare Center (June 18, 2005)



#3 - Transformer prior to damage (June 18, 2005)



“Distribution Transformer”



#5 -Transformer marked "Perclene Filled"
(July 15, 2005)



#6 - Damaged transformer is placed on demolition debris pile (July 15, 2005)



#7 - Damaged transformer and demolition debris (July 15, 2005)



#8 - Damaged transformer wrapped with plastic (July 19, 2005)



#9 - Drums containing PCE and roll-off bin
containing PCE-contaminated debris
(July 19, 2005)

